

# Kraftsteckschlüssel mit Spindelführung – Antrieb 1/2“



## Sechskant – mit Magnet

| Modell     | Best.-Nr. | SW mm | Form | L mm | D1 mm | D2 mm | L2 mm |
|------------|-----------|-------|------|------|-------|-------|-------|
| KHM 1/2-10 | 310410    | 10    | AS   | 52   | 17,5  | 25    | 8     |
| KHM 1/2-11 | 310411    | 11    | AS   | 52   | 18,5  | 25    | 9     |
| KHM 1/2-12 | 310412    | 12    | AS   | 52   | 20    | 25    | 12    |
| KHM 1/2-13 | 310413    | 13    | AS   | 52   | 21    | 25    | 12    |
| KHM 1/2-14 | 310414    | 14    | AS   | 52   | 22,5  | 25    | 12    |
| KHM 1/2-15 | 310415    | 15    | AS   | 52   | 23,5  | 30    | 12    |
| KHM 1/2-16 | 310416    | 16    | AS   | 52   | 25    | 30    | 12    |
| KHM 1/2-17 | 310417    | 17    | AS   | 52   | 26    | 30    | 12    |
| KHM 1/2-18 | 310418    | 18    | AS   | 52   | 27,5  | 30    | 12    |
| KHM 1/2-19 | 310419    | 19    | AS   | 52   | 28,5  | 30    | 12    |
| KHM 1/2-20 | 310420    | 20    | BS   | 52   | 30    | 30    | 12    |
| KHM 1/2-21 | 310421    | 21    | CS   | 52   | 31    | 30    | 12    |
| KHM 1/2-22 | 310422    | 22    | CS   | 52   | 32    | 30    | 12    |
| KHM 1/2-23 | 310423    | 23    | CS   | 52   | 34    | 30    | 12    |
| KHM 1/2-24 | 310424    | 24    | CS   | 52   | 35    | 30    | 12    |
| KHM 1/2-25 | 310425    | 25    | CS   | 57   | 36    | 30    | 12    |
| KHM 1/2-26 | 310426    | 26    | CS   | 57   | 38    | 30    | 12    |
| KHM 1/2-27 | 310427    | 27    | CS   | 57   | 38,5  | 30    | 12    |




## Sechskant – tief – mit Magnet

| Modell      | Best.-Nr. | SW mm | Form | L mm | D1 mm | D2 mm | L2 mm |
|-------------|-----------|-------|------|------|-------|-------|-------|
| KHM 1/2-10T | 310330    | 10    | FS   | 100  | 17,5  | 25    | 5     |
| KHM 1/2-13T | 310333    | 13    | FS   | 100  | 21    | 25    | 6     |
| KHM 1/2-16T | 310336    | 16    | FS   | 100  | 25    | 30    | 7     |
| KHM 1/2-17T | 310337    | 17    | FS   | 100  | 26    | 30    | 7     |
| KHM 1/2-19T | 310339    | 19    | FS   | 100  | 28,5  | 30    | 8     |


## Sechskant – XL – mit Magnet

| Modell         | Best.-Nr. | SW mm | Form | L mm | D1 mm | D2 mm | L2 mm |
|----------------|-----------|-------|------|------|-------|-------|-------|
| KHM 1/2-10-100 | 310210    | 10    | DS   | 100  | 17,5  | 25    | 4     |
| KHM 1/2-11-100 | 310211    | 11    | DS   | 100  | 18,5  | 25    | 5     |
| KHM 1/2-12-100 | 310212    | 12    | DS   | 100  | 20    | 25    | 5     |
| KHM 1/2-13-100 | 310213    | 13    | DS   | 100  | 21    | 25    | 6     |
| KHM 1/2-14-100 | 310214    | 14    | DS   | 100  | 22,5  | 25    | 6     |
| KHM 1/2-15-100 | 310215    | 15    | DS   | 100  | 23,5  | 30    | 7     |
| KHM 1/2-16-100 | 310216    | 16    | DS   | 100  | 25    | 30    | 7     |
| KHM 1/2-17-100 | 310217    | 17    | DS   | 100  | 26    | 30    | 7     |
| KHM 1/2-18-100 | 310218    | 18    | DS   | 100  | 27,5  | 30    | 8     |
| KHM 1/2-19-100 | 310219    | 19    | DS   | 100  | 28,5  | 30    | 8     |
| KHM 1/2-10-150 | 310250    | 10    | DS   | 150  | 17,5  | 25    | 12    |
| KHM 1/2-11-150 | 310251    | 11    | DS   | 150  | 18,5  | 25    | 12    |
| KHM 1/2-12-150 | 310252    | 12    | DS   | 150  | 20    | 25    | 12    |
| KHM 1/2-13-150 | 310253    | 13    | DS   | 150  | 21    | 25    | 12    |
| KHM 1/2-14-150 | 310254    | 14    | DS   | 150  | 22,5  | 25    | 12    |
| KHM 1/2-15-150 | 310255    | 15    | DS   | 150  | 23,5  | 30    | 12    |
| KHM 1/2-16-150 | 310256    | 16    | DS   | 150  | 25    | 30    | 13    |
| KHM 1/2-17-150 | 310257    | 17    | DS   | 150  | 26    | 30    | 13    |
| KHM 1/2-18-150 | 310258    | 18    | DS   | 150  | 27,5  | 30    | 13    |
| KHM 1/2-19-150 | 310259    | 19    | DS   | 150  | 28,5  | 30    | 13    |
| KHM 1/2-10-200 | 310310    | 10    | DS   | 200  | 17,5  | 25    | 12    |
| KHM 1/2-11-200 | 310311    | 11    | DS   | 200  | 18,5  | 25    | 12    |
| KHM 1/2-12-200 | 310312    | 12    | DS   | 200  | 20    | 25    | 12    |
| KHM 1/2-13-200 | 310313    | 13    | DS   | 200  | 21    | 25    | 12    |
| KHM 1/2-14-200 | 310314    | 14    | DS   | 200  | 22,5  | 25    | 12    |
| KHM 1/2-15-200 | 310315    | 15    | DS   | 200  | 23,5  | 30    | 12    |
| KHM 1/2-16-200 | 310316    | 16    | DS   | 200  | 25    | 30    | 13    |
| KHM 1/2-17-200 | 310317    | 17    | DS   | 200  | 26    | 30    | 13    |
| KHM 1/2-18-200 | 310318    | 18    | DS   | 200  | 27,5  | 30    | 13    |
| KHM 1/2-19-200 | 310319    | 19    | DS   | 200  | 28,5  | 30    | 13    |

Form AS



Form DS



Form FS

