

1/2 Power Sockets with Sleeve Drive – Square Drive 1/2"



Hex Driver (Allen)

Model	Item No.	A/F mm	Form	L mm	D1 mm	D2 mm	L2 mm
KH 1/2-A3	310350	3	ES	75	–	25	11
KH 1/2-A4	310351	4	ES	75	–	25	11
KH 1/2-A5	310352	5	ES	75	–	25	15
KH 1/2-A6	310353	6	ES	75	–	25	15
KH 1/2-A7	310354	7	ES	75	–	25	20
KH 1/2-A8	310355	8	ES	75	–	25	25
KH 1/2-A9	310356	9	ES	75	–	25	25
KH 1/2-A10	310357	10	ES	75	–	25	25
KH 1/2-A11	310358	11	ES	75	–	25	25
KH 1/2-A12	310359	12	ES	75	–	25	25
KH 1/2-A13	310360	13	ES	75	–	25	25
KH 1/2-A14	310361	14	ES	75	–	25	25
KH 1/2-A15	310362	15	ES	75	–	25	25
KH 1/2-A16	310363	16	ES	75	–	25	25
KH 1/2-A17	310364	17	ES	75	–	25	25
KH 1/2-A18	310365	18	ES	75	–	25	25
KH 1/2-A19	310366	19	ES	75	–	25	25

Torx® Driver (TX)

Model	Item No.	Torx #	Form	L mm	D1 mm	D2 mm	L2 mm
KH 1/2-T20	310510	T20	ES	75	–	25	2,8
KH 1/2-T25	310511	T25	ES	75	–	25	3
KH 1/2-T27	310512	T27	ES	75	–	25	3
KH 1/2-T30	310513	T30	ES	75	–	25	3,8
KH 1/2-T40	310514	T40	ES	75	–	25	3,8
KH 1/2-T45	310515	T45	ES	75	–	25	4,3
KH 1/2-T47	310516	T47	ES	75	–	25	5
KH 1/2-T50	310517	T50	ES	75	–	25	5
KH 1/2-T55	310518	T55	ES	75	–	25	5,5
KH 1/2-T60	310519	T60	ES	75	–	25	8
KH 1/2-T70	310520	T70	ES	75	–	25	9,4
KH 1/2-T80	310521	T80	ES	75	–	25	10,5
KH 1/2-T90	310522	T90	ES	75	–	25	11,8
KH 1/2-T100	310523	T100	ES	75	–	25	13,1

Custom-made products

INFO

Do you need individual special sockets? We also manufacture special tools according to drawings. Please contact us. We will be happy to provide you with a non-binding offer.


Application advise

INFO

Worn sockets cause a loss of power and also wear out the square drive of the tool. This also causes increasing vibrations, which makes working more difficult.

Worn power sockets should therefore be replaced at an early stage.

Form ES



Further information available 24 / 7 on our website.