

# 1/2" Power Sockets with Sleeve Drive – Square Drive 1/2"



## 6-point – with magnet

Model	Item No.	A/F mm	Form	L mm	D1 mm	D2 mm	L2 mm
KHM 1/2-6	310406	6	AS	52	13	25	5
KHM 1/2-7	310407	7	AS	52	14	25	5
KHM 1/2-8	310408	8	AS	52	15	25	7
KHM 1/2-9	310409	9	AS	52	16	25	7
KHM 1/2-10	310410	10	AS	52	17.5	25	8
KHM 1/2-11	310411	11	AS	52	18.5	25	9
KHM 1/2-12	310412	12	BS	52	20	25	12
KHM 1/2-13	310413	13	AS	52	21	25	12
KHM 1/2-14	310414	14	AS	52	22.5	25	12
KHM 1/2-15	310415	15	AS	52	23.5	30	12
KHM 1/2-16	310416	16	AS	52	25	30	12
KHM 1/2-17	310417	17	AS	52	26	30	12
KHM 1/2-18	310418	18	AS	52	27.5	30	12
KHM 1/2-19	310419	19	AS	52	28.5	30	12
KHM 1/2-20	310420	20	BS	52	30	30	12
KHM 1/2-21	310421	21	CS	52	31	30	12
KHM 1/2-22	310422	22	CS	52	32	30	12
KHM 1/2-23	310423	23	CS	52	34	30	12
KHM 1/2-24	310424	24	CS	52	35	30	12
KHM 1/2-25	310425	25	CS	57	36	30	12
KHM 1/2-26	310426	26	CS	57	38	30	12
KHM 1/2-27	310427	27	CS	57	38.5	30	12

## 6-point – XL – with magnet


Model	Item No.	A/F mm	Form	L mm	D1 mm	D2 mm	L2 mm
KHM 1/2-10-100	310210	10	DS	100	17.5	25	4
KHM 1/2-11-100	310211	11	DS	100	18.5	25	5
KHM 1/2-12-100	310212	12	DS	100	20	25	5
KHM 1/2-13-100	310213	13	DS	100	21	25	6
KHM 1/2-14-100	310214	14	DS	100	22.5	25	6
KHM 1/2-15-100	310215	15	DS	100	23.5	30	7
KHM 1/2-16-100	310216	16	DS	100	25	30	7
KHM 1/2-17-100	310217	17	DS	100	26	30	7
KHM 1/2-18-100	310218	18	DS	100	27.5	30	8
KHM 1/2-19-100	310219	19	DS	100	28.5	30	8
KHM 1/2-10-150	310250	10	DS	150	17.5	25	12
KHM 1/2-11-150	310251	11	DS	150	18.5	25	12
KHM 1/2-12-150	310252	12	DS	150	20	25	12
KHM 1/2-13-150	310253	13	DS	150	21	25	12
KHM 1/2-14-150	310254	14	DS	150	22.5	25	12
KHM 1/2-15-150	310255	15	DS	150	23.5	30	12
KHM 1/2-16-150	310256	16	DS	150	25	30	13
KHM 1/2-17-150	310257	17	DS	150	26	30	13
KHM 1/2-18-150	310258	18	DS	150	27.5	30	13
KHM 1/2-19-150	310259	19	DS	150	28.5	30	13
KHM 1/2-10-200	310310	10	DS	200	17.5	25	12
KHM 1/2-11-200	310311	11	DS	200	18.5	25	12
KHM 1/2-12-200	310312	12	DS	200	20	25	12
KHM 1/2-13-200	310313	13	DS	200	21	25	12
KHM 1/2-14-200	310314	14	DS	200	22.5	25	12
KHM 1/2-15-200	310315	15	DS	200	23.5	30	12
KHM 1/2-16-200	310316	16	DS	200	25	30	13
KHM 1/2-17-200	310317	17	DS	200	26	30	13
KHM 1/2-18-200	310318	18	DS	200	27.5	30	13
KHM 1/2-19-200	310319	19	DS	200	28.5	30	13




## 6-point – deep – with magnet

Model	Item No.	A/F mm	Form	L mm	D1 mm	D2 mm	L2 mm
KHM 1/2-10T	310330	10	FS	100	17,5	25	5
KHM 1/2-13T	310333	13	FS	100	21	25	6
KHM 1/2-16T	310336	16	FS	100	25	30	7
KHM 1/2-17T	310337	17	FS	100	26	30	7
KHM 1/2-19T	310339	19	FS	100	28,5	30	8

Form AS



Form DS



Form FS

